

Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

RE: Bldg. #1 Railing

1 message

Tony Taylor <ttaylor@caasti.com>

Tue, Aug 20, 2013 at 2:49 PM

To: Jerry Carter < Jerry.Carter@smithgroupjjr.com>

Cc: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>, ctaylor@caasti.com, Linda Randle

<lrandle@caasti.com>

Ok thanks.

Tony A. Taylor

Sr. Estimator/Project Manager

Caasti Contracting Svcs.

19115 W. Eight Mile Rd.

Detriot, Mi.48219

313-535-9891 Office

313-535-9896 fax

ttaylor@caasti.com

From: Jerry Carter [mailto:Jerry.Carter@smithgroupjjr.com]

Sent: Tuesday, August 20, 2013 3:26 PM

To: Tony Taylor


Cc: 'Steven Yamasaki - 5PSSC1B'; ctaylor@caasti.com; 'Linda Randle'

Subject: RE: Bldg. #1 Railing

Tony please refer to RFI #11 response for this item.

Thanks,

Jerry



From: Tony Taylor [mailto:ttaylor@caasti.com]
Sent: Tuesday, August 20, 2013 2:03 PM

To: Jerry Carter

Cc: 'Steven Yamasaki - 5PSSC1B'; ctaylor@caasti.com; 'Linda Randle'

Subject: FW: Bldg. #1 Railing

Jerry, please see email below stating the railing locations in the drawing.

Thanks.

Tony A. Taylor

Sr. Estimator/Project Manager

Caasti Contracting Svcs.

19115 W. Eight Mile Rd.

Detriot, Mi.48219

313-535-9891 Office

313-535-9896 fax

ttaylor@caasti.com

From: linda robbins

Sent: Tuesday, August 20, 2013 12:56 PM

To: Tony Taylor

Subject: Re: Bldg. #1 Railing

One - Rail -1R4 is stairway A

One - Rail - 1R2 is the west rail on sheet A107

One - Rail - 1R1 is the east rail on sheet A107

Two - Rail - 1R3 is stairway B & C

However, please let them know we are not asking that they



Steven Yamasaki - SPSSC1B <steven.yamasaki@gsa.gov>

RE: Bldg. #1 Railing

1 message

Jerry Carter < Jerry. Carter@smithgroupjjr.com>

Tue, Aug 20, 2013 at 2:26 PM

To: Tony Taylor <ttaylor@caasti.com>

Cc: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>, "ctaylor@caasti.com" <ctaylor@caasti.com>, Linda Randle <lrandle@caasti.com>

Tony please refer to RFI #11 response for this item.

Thanks,

Jerry

From: Tony Taylor [mailto:ttaylor@caasti.com] Sent: Tuesday, August 20, 2013 2:03 PM

To: Jerry Carter

Cc: 'Steven Yamasaki - 5PSSC1B'; ctaylor@caasti.com; 'Linda Randle'

Subject: FW: Bldg. #1 Railing

Jerry, please see email below stating the railing locations in the drawing.

Thanks.

Tony A. Taylor

Sr. Estimator/Project Manager

Caasti Contracting Svcs.

19115 W. Eight Mile Rd.

Detriot, Mi.48219

313-535-9891 Office

313-535-9896 fax

ttaylor@caasti.com

From: linda robbins

Sent: Tuesday, August 20, 2013 12:56 PM

To: Tony Taylor

Subject: Re: Bldg. #1 Railing

One - Rail -1R4 is stairway A

One - Rail - 1R2 is the west rail on sheet A107

One - Rail - 1R1 is the east rail on sheet A107

Two - Rail - 1R3 is stairway B & C

However, please let them know we are not asking that they verify measurements for proper fit, we are asking for authorization to change not having looped ends and the dimension of the looped ends as we are now using the existing holes.

Linda Robbins R.B. Christian Inc.

From: Jerry Carter Sent: Friday, August 16, 2013 3:23 PM

To: Tony Taylor

Subject: RE: Bldg. #1 Railing

Tony,

Per our discussion during the meeting this week, please indicate which sketch is for which stair (see attached).

Thanks,



Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

FW: Bldg. #1 Railing

1 message

Tony Taylor <ttaylor@caasti.com>

Tue, Aug 20, 2013 at 1:03 PM

To: Jerry Carter < Jerry.Carter@smithgroupjjr.com>

Cc: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>, ctaylor@caasti.com, Linda Randle

<lrandle@caasti.com>

Jerry, please see email below stating the railing locations in the drawing.

Thanks.

Tony A. Taylor

Sr. Estimator/Project Manager

Caasti Contracting Svcs.

19115 W. Eight Mile Rd.

Detriot, Mi.48219

313-535-9891 Office

313-535-9896 fax

ttaylor@caasti.com

From: linda robbins

Sent: Tuesday, August 20, 2013 12:56 PM

To: Tony Taylor

Subject: Re: Bldg. #1 Railing

One - Rail -1R4 is stairway A

One - Rail - 1R2 is the west rail on sheet A107

One - Rail - 1R1 is the east rail on sheet A107

Two - Rail - 1R3 is stairway B & C

However, please let them know we are not asking that they verify measurements for proper fit, we are asking for authorization to change not having looped ends and the dimension of the looped ends as we are now using the existing holes.

Linda Robbins R.B. Christian Inc.

From: Jerry Carter Sent: Friday, August 16, 2013 3:23 PM

To: Tony Taylor

Subject: RE: Bldg. #1 Railing

Tony,

Per our discussion during the meeting this week, please indicate which sketch is for which stair (see attached).

Thanks,

Jerry



Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Re: Building 1 Walkway Railing Options

1 message

David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>

Mon, Aug 19, 2013 at 8:23 AM

To: Jerry Carter < Jerry. Carter@smithgroupjjr.com>, Steven Yamasaki - 5PSSC1B < steven.yamasaki@gsa.gov>

Jerry

Lets go with option 2. I'd rather not drill or plug additional holes. I can live with the minor differences in profile with the existing.

Thanks

On Fri, Aug 16, 2013 at 5:26 PM, Jerry Carter < Jerry.Carter@smithgroupjjr.com> wrote: Dave.

Per our discussion during the last site meeting please see the attached pdf and summary below for the building 1 walkway railing options.

Summary of Options:

Options 1 & 2 are recommended by SGJJR.

Option 3 matches what the contract documents indicate and reflect the railing post locations. Note, Caasti has installed the temporary railings and the post locations are now determined.

Options 4 & 5 are similar to the railings for the building 1 ramps, however, this option requires the post location at the bottom of the stair to be moved. SGJJR does not recommend these two options.

Option 6 matches the sketch from Tony's sub-contractor.

I will give you a call on Monday to discuss the attached sketches.

Regards,

Jerry

Jerry Carter

Building Technology Studio

SmithGroupJJR

500 Griswold, Suite 1700 Detroit, MI 48226

t 313.983.3600 d 313.442.8123 f 734.780.2432

Jerry.Carter@smithgroupjjr.com<mailto:Jerry.Carter@smithgroupjjr.com>

Expect the Unexpected.

Visit www.smithgroupjjr.comhttp://www.smithgroupjjr.com/>

Follow us on LinkedInhttp://www.linkedin.com/company/SmithGroupJJR | @SmithGroupJJRhttp://twitter.com/@SmithGroupJJR

David Kamrowski
Property Manager, Battle Creek Field Office
GSA, PBS Great Lakes Region, MISC, PMSC
Hart-Dole-Inouye Federal Center, 74 N. Washington Ave.
Battle Creek, Michigan 49037-3086
269-425-3353, (b) (6) fax 269-961-7345
david.kamrowski@gsa.gov
www.gsa.gov/hdifedctr



Steven Yamasaki - 5PSSC1B < steven.yamasaki@gsa.gov>

Re: Bldg. 1 Railing Crew Information

1 message

ctaylor@caasti.com <ctaylor@caasti.com>

Mon, Sep 23, 2013 at 12:30 PM

Reply-To: "ctaylor@caasti.com" <ctaylor@caasti.com>

To: Steve Adams <act1001@aol.com>, Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>, David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>

I am aware of this fact Dave. I thought that ou still needed their information on file so that you know who is on site. Please advise.

On September 23, 2013 at 1:25 PM David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov> wrote:

Candice.

Neither worker has a current clearance to work on GSA property. They will require CAASTI to provide an escort for them.

On Mon, Sep 23, 2013 at 12:09 PM, ctaylor@caasti.com <ctaylor@caasti.com> wrote:

Dave, Please see attached names for the crew that will be doing the install for Building 1 railings. I havent forwarded you a schedule yet but I wanted to get these names to you asap. Also, I will be on AM MUE WORLD site with one of my subs tomorrow around 11 or 12. Please let me know if you have any quesions.

Thanks

----- Original Message -----

From: Dorothy < djm@oikindustries.com>

To: ctaylor@caasti.com

Date: September 19, 2013 at 11:00 AM

Subject: Battle Creek Federal Bldg. Crew Information Requested

Good Morning Candice,

Tim ask me to forward some information on our installation crew. I have attached copies of Drivers License for Todd Buchanan and Ryan Scheffers.

They will be doing the first install and it will be 2 days. Please note that the copy of Todd's license is expired. I will forwarded the current one when I see him. He is out on an installation today. So it will be Todd and Ryan on the first two days and the remaining installation will be done with 2 additional people. I will forward the rest of the info on them after lunch.

Todd Buchanan



License No.:



Ryan Scheffers

DOB:

Thank You,

Dorothy

Candice Taylor

CAASTI Contracting Services, Inc.

19115 West Eight Mile Rd

Detroit, MI 48219

313-535-9891 office / 313-535-9896

Every situation properly perceived becomes an opportunity

David Kamrowski
Property Manager, Battle Creek Field Office
GSA, PBS Great Lakes Region, MISC, PMSC
Hart-Dole-Inouye Federal Center, 74 N. Washington Ave.
Battle Creek, Michigan 49037-3086
269-425-3353, (b) (6) fax 269-961-7345
david.kamrowski@gsa.gov
www.gsa.gov/hdifedctr

Candice Taylor

CAASTI Contracting Services, Inc.

19115 West Eight Mile Rd

Detroit, MI 48219

313-535-9891 office / 313-535-9896

Every situation properly perceived becomes an opportunity



Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Fwd: Bldg. 1 Railing Crew Information

1 message

Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Thu, Sep 26, 2013 at 2:35 PM

To: Candice Taylor <ctaylor@caasti.com>

Cc: Dave Kamrowski <david.kamrowski@gsa.gov>, Kathern Williams - 5P2PQBC <kathern.williams@gsa.gov>, "act1001@aol.com" <act1001@aol.com>, Jerry Carter <Jerry.Carter@smithgroupjjr.com>

Please provide escorts and coordinate with Dave K.

Steve

----- Forwarded message -----

From: David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>

Date: Thu, Sep 26, 2013 at 2:32 PM

Subject: Fwd: Bldg. 1 Railing Crew Information

To: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Steve, here is my response on the railing contractors.

----- Forwarded message ------

From: David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>

Date: Mon, Sep 23, 2013 at 1:25 PM

Subject: Re: Bldg. 1 Railing Crew Information

To: "ctaylor@caasti.com" <ctaylor@caasti.com>, Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>,

Steve Adams <act1001@aol.com>

Candice,

Neither worker has a current clearance to work on GSA property. They will require CAASTI to provide an escort for them.

On Mon, Sep 23, 2013 at 12:09 PM, ctaylor@caasti.com <ctaylor@caasti.com> wrote:

Dave, Please see attached names for the crew that will be doing the install for Building 1 railings. I havent forwarded you a schedule yet but I wanted to get these names to you asap. Also, I will be on site with one of my subs tomorrow around 11 or 12. Please let me know if you have any quesions.

Thanks

----- Original Message -----

From: Dorothy <djm@oikindustries.com>

To: ctaylor@caasti.com

Date: September 19, 2013 at 11:00 AM

Subject: Battle Creek Federal Bldg. Crew Information Requested

Good Morning Candice,

Tim ask me to forward some information on our installation crew. I have attached copies of Drivers License for Todd Buchanan and Ryan Scheffers.

They will be doing the first install and it will be 2 days. Please note that the copy of Todd's license is expired. I will forwarded the current one when I see him. He is out on an installation today. So it will be Todd and Ryan on the first two days and the remaining installation will be done with 2 additional people. I will forward the rest of the info on them after lunch.

Todd Buchanan


Ryan Scheffers

DOB:

DOB:

License No.:

License No.:



Thank You,

Dorothy

Candice Taylor

CAASTI Contracting Services, Inc.

19115 West Eight Mile Rd

Detroit, MI 48219

313-535-9891 office / 313-535-9896

Every situation properly perceived becomes an opportunity

David Kamrowski
Property Manager, Battle Creek Field Office
GSA, PBS Great Lakes Region, MISC, PMSC
Hart-Dole-Inouye Federal Center, 74 N. Washington Ave.
Battle Creek, Michigan 49037-3086
269-425-3353, (b) (6) fax 269-961-7345
david.kamrowski@gsa.gov
www.gsa.gov/hdifedctr

David Kamrowski Property Manager, Battle Creek Field Office



Steven Varrasek) - SPSSC16 Kitaves, varrasakk@geo.gov-

CAASTI during shut down

1 16955800

David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>
To: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Mon, Oct 21, 2013 at 2:25 PM

Steve, During the shutdown, and I can't pin point which days, I had two separate instances where I had to tell CAASTI or their subs they could not work.

The first was Tichnor showed up to work on the roof of Bldg 5. I would not grant access.

Several days later Candice called to schedule a time to install the hand rails in the front walkway. I informed her they could not work as CAASTI had been sent a stop work order due to the government shut down.

Thanks

David Kamrowski
Property Manager, Battle Creek Field Office
GSA, PBS Great Lakes Region, MISC, PMSC
Hart-Dole-Inouye Federal Center, 74 N. Washington Ave.
Battle Creek, Michigan 49037-3086
269-425-3353, (b) (6) fax 269-961-7345
david.kamrowski@gsa.gov
www.gsa.gov/hdifedctr





Steven Yemaseid - SPESCIB Keleven yamasaki@gsa.quv-

Fwd:

1 message

Steven Yamasaki - 5PSSC1B < steven.yamasaki@gsa.gov>

Thu, Nov 21, 2013 at 9:05 AM

To: Jerry Carter < Jerry.Carter@smithgroupjjr.com>

Cc: "act1001@aol.com" <act1001@aol.com>, Dave Kamrowski <david.kamrowski@gsa.gov>

Jerry: Can you comment and forward the approved shop drawing please.

Steve

----- Forwarded message -----

From: David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>

Date: Thu, Nov 21, 2013 at 8:48 AM

Subject: Fwd:

To: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Steve,

This is the hand rail demonstrated on A107, lower right corner.

Is this what the submittal showed?

These are new steps and the original location of the rail should not have been a contributing factor.

Two potential issues. The leading edge usually protrudes 12" beyond the end of the step and I would have expected the lower post to have been in the sidewalk not the step. I do not take issue with the post being in the step, it makes sidewalk snow removal easier for us, but the extension should be manufactured appropriately (if it isn't)

Second issue and the most important, look at the way the extension is attached to the post. Most applications the lower extension is aligned with the lower rail. The other new rails do, why doesn't this one? Please check the submittal to ensure this rail adheres to the submittal as approved.

Other than that, the hand rails at the front of Bldg 1 are installed and look like a good.

Thanks

David Kamrowski
Property Manager, Battle Creek Field Office
GSA, PBS Great Lakes Region, MISC, PMSC
Hart-Dole-Inouye Federal Center, 74 N. Washington Ave.
Battle Creek, Michigan 49037-3086
269-425-3353, (b) (6) fax 269-961-7345
david.kamrowski@gsa.gov
www.gsa.gov/hdifedctr

Steve Yamasaki Project Manager,MISC Technical team GSA, PBS, Great Lakes Region, PMSC 230 South Dearborn Street Suite 3300 Chicago, IL 60604

(312) 353-1256 (b) (6)

fax (312) 353-0240

steven.yamasaki@gsa.gov



IMG_20131121_082020_450.jpg 985K



Steven Yemasald - SPSECHI Paleven yamasali@qaa.gov-

RE: Fwd:

1 инсьици

Jerry Carter < Jerry. Carter@smithgroupjjr.com>

Thu, Nov 21, 2013 at 10:29 AM

To: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Cc: "act1001@aol.com" <act1001@aol.com>, Dave Kamrowski <david.kamrowski@gsa.gov>

See attached approved shop drawings for building 1 railings.

The installation of this railing does not match the shop drawings. The shop drawings indicate the railing post in the sidewalk, which would allow the extension to be 12'' (2'' post + 10'' extension) from the last step. The installation does not meet code.

From: Steven Yamasaki - 5PSSC1B [mailto:steven.yamasaki@gsa.gov]

Sent: Thursday, November 21, 2013 10:06 AM

To: Jerry Carter

Cc: act1001@aol.com; Dave Kamrowski

Subject: Fwd:

Jerry: Can you comment and forward the approved shop drawing please.

Steve

----- Forwarded message -----

From: David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>

Date: Thu, Nov 21, 2013 at 8:48 AM

Subject: Fwd:

To: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Steve,

This is the hand rail demonstrated on A107, lower right corner.

Is this what the submittal showed?

These are new steps and the original location of the rail should not have been a contributing factor.

Two potential issues. The leading edge usually protrudes 12" beyond the end of the step and I would have expected the lower post to have been in the sidewalk not the step. I do not take issue with the post being in the step, it makes sidewalk snow removal easier for us, but the extension should be manufactured appropriately (if it isn't)

Second issue and the most important, look at the way the extension is attached to the post. Most applications the lower extension is aligned with the lower rail. The other new rails do, why doesn't this one? Please check the submittal to ensure this rail adheres to the submittal as approved.

Other than that, the hand rails at the front of Bldg 1 are installed and look like a good.

Thanks

David Kamrowski
Property Manager, Battle Creek Field Office
GSA, PBS Great Lakes Region, MISC, PMSC
Hart-Dole-Inouye Federal Center, 74 N. Washington Ave.
Battle Creek, Michigan 49037-3086
269-425-3353, (b) (6) fax 269-961-7345
david.kamrowski@gsa.gov
www.gsa.gov/hdifedctr

Steve Yamasaki

Project Manager, MISC Technical team

GSA, PBS, Great Lakes Region, PMSC

230 South Dearborn Street Suite 3300

Chicago, IL 60604

(312) 353-1256 (b) (6) fax (312) 353-0240

steven.yamasaki@gsa.gov

007C - Revised Handrail Bldg 1.pdf 222K





CAASTI Contracting Services
19115 West Eight Mile Rd • Detroit, MI 48219 (313) 535-9891 office • (313) 535-9896 fax

SmithGroup SG->CAASTI 09.17.13

			TRANSMITTAL	·		
	No: To:	#7C Smith Group 500 Griswold S Detroit, Michiga Attention: Paul	I G. Johnson aki, Alice Wellams, Steven Adams, David Kamrowski, JoAnn Taylor, Candice Taylor ye U S Federal Center – Battle Creek, MI acting / Candice Taylor ght Mile Rd			
	CC: Project:	 Tony Taylor & 0 				
	From:					
	We are send	ding: x Attached	Under Separate Cover			
	The following:		Specifications x Submittal	Other		
	Qty	Date	Description	Comment Action		
	5	9/11/2013	R B Christian Bldg. 1 Revised Shop Drawings for Railings	A		
ppı ppı isa	nt/Action Co roved roved as Not pprove, Res on Not Requi	ed ubmit				
		Files x Approv	valReview & Comment Use Ot	her		
our	: <u>x</u>					

09.17.13

R. B. Christian

Since 1952

Metal Fabrication

Pre-Cast Concrete

439 W. Columbia Ave. Battle Creek, Michigan 49015 Phone (269) 963-2222 Fax (269) 963-1756 3523 S. Cedar St. Lansing, Michigan 48910 (517) 882-9100 Email christianinc@att.net

TRANSMITTAL

September 10, 2013

To: Tony Taylor, Caasti Contracting Services


Re: Revision of shop drawings for Building 1 walkway


1.) All material to stay the same

2.) All railings to be clear anodized as stated in original shop drawing


3.) All post installation to be same as original shop drawings


4.) All handrails are capable of withstanding a uniform load of 50 lbs./ft. and a concentrated load of 200 lbs./ft. Applied to handrails and top rails in any direction.





Clata # S ALUM ESCUTCHEON
(SEE PLOGUET P.Z.)
Shert # Z.) 11 FO SCH 40 ALUM, PIPE - HORIZ. (See pri 3,-0, .0-.1 %; %; 3.617,18 27.5 . P. 7 ..8<mark>%</mark>6-,6 ONE - RAIL - 1R2 Llest rail on sheet AIOT ICLEAR ANODIZED BEVEL: 9.7° * Hart-Doyle-Inouye Federal Center Roof Replacement & Masonry Restoration Project Job No: GS-05P-12-SV-C-0035 1.21% 10 Battle Creek, MI 49015 269-963-2222 439 W. Columbia Ave. R.B. Christian Inc. ,,O-,1 3.-0. 3.0









DECEIVED SEP 16 2013

CAASTI Contracting Services

19115 West Eight Mile Rd • Detroit, MI 48219 (313) 535-9891 office • (313) 535-9896 fax

SmithGroup SG>CAASTI 09.17.13

L		TRANSMITTAL				
No: To:	#7C Smith Group 500 Griswold St Detroit, Michiga Attention: Paul					
CC: Project:	Steven Yamasaki, Alice Wellams, Steven Adams, David Kamrowski, JoAnn Taylor, Tony Taylor & Candice Taylor Hart-Dole-Inouye U S Federal Center – Battle Creek, MI					
From:	CAASTI Contra 19115 West Eig Detroit, MI 482	cting / Candice Taylor pht Mile Rd 19				
We are sen	nding: x Attached	Under Separate Cover				
The following	ng: Drawings	Specifications x Submittal	Other			
Qty	Date	Description	Comment	Action		
5	9/11/2013	R B Christian – Bidg. 1 Revised Shop Drawings for Railings		A		
nent/Action Coproved as No sapprove, Restion Not Requ	oted submit					
our: <u>x</u>		**************************************	ther			
	'i baa yayiayaad dha ay	ibmittals and has been approved. Electronic C	Copy was em	ailed on 9		

Recvd By

R. B. Christian

Since 1952

Metal Fabrication

Pre-Cast Concrete

439 W. Columbia Ave. Battle Creek, Michigan 49015 Phone (269) 963-2222 Fax (269) 963-1756

3523 S. Cedar St. Lansing, Michigan 48910 (517) 882-9100 Email christianinc@att.net

TRANSMITTAL

September 10, 2013

To: Tony Taylor, Caasti Contracting Services


Re: Revision of shop drawings for Building 1 walkway


1.) All material to stay the same

2.) All railings to be clear anodized as stated in original shop drawing


3.) All post installation to be same as original shop drawings

4.) All handrails are capable of withstanding a uniform load of 50 lbs./ft. and a concentrated load of 200 lbs./ft. Applied to handrails and top rails in any direction.





Clater #5) ALUM ESCUTCHEON
(SEE PLOGUET OF 2)
Shert of 2) 1 \$78 SCH 40 ALUM, PIPE - HORIZ 1 \$78 SCH 80 ALUM, PIPE - POSTS Joyd Jas 3.-0, .0-.1 6%;e 3.61,16 17.7 . 77. 7.7. ONE - RAIL - 1R2 Nest rail on sheet AIOT CY EAR ANODIZED BEVEL: 9.7° * Hart-Doyle-Inouye Federal Center Roof Replacement & Masonry Job No: GS-05P-12-SV-C-0035 1.21% Battle Creek, MI 49015 269-963-2222 439 W. Columbia Ave. Restoration Project R.B. Christian Inc. 1,0,1 .O-.E .0·.C





Steven Yamasətü - SPSSSP1 refeven yamasatiğiyesi iyevi

Making sense of the Photos

1 measage

David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>
To: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Mon, Nov 25, 2013 at 1:50 PM

Photos 1360 and 1361 are of the SE rail. It looks like the submital but it does not extend the proper distance beyond the bottom step and the lower post is in the step not the landing.

1362 and 1363 are of the SW rail. It also does not extend beyond the bottom step correctly and the lower post is in the step not the landing.

1364 and 1365 are of stair "A". Post are correctly located but lower rail does not line up with the lower end of the extension. Please compare to submital drawing

1366 and 1367 are of stair "B" Post are correct and lower rail alignment seem correct.


1368 and 1369 are of stair "C". Post are correct and lower rail alignment seem correct.

Thanks

David Kamrowski
Property Manager
GSA/PBS Michigan Property Management Operations Branch
74 N. Washington Avenue, Room 2-1-6
Battle Creek, MI 49037
269-425-3353, (b) (6) fax 269-961-7345

david.kamrowski@gsa.gov

www.gsa.gov/hdifedctr



								2.0
:								
í L								
i k							·	
								a.
j		•						
ie Se								
i								
		÷ .		:				
		•						
			and the second					
			\$					
				•		•		
N.								
Š		•						
	-		,			,		
			•					
			*					.*
9								
Y Y								
	•	ı						
Ų.		•			·			
		•						
	•							
		_	-					
i i			•					



Steven Yanasaki - SPSSSP1 Kdeven yamasaki@gsa.gov-

Pictures 1 of 2

1 TAYGOLD JACK

David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>
To: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Mon, Nov 25, 2013 at 1:33 PM


David Kamrowski
Property Manager
GSA/PBS Michigan Property Management Operations Branch
74 N. Washington Avenue, Room 2-1-6
Battle Creek, MI 49037

269-425-3353, (b) (6)

fax 269-961-7345


david.kamrowski@gsa.gov www.gsa.gov/hdifedctr

8 attachments





IMG_1360[1].JPG 3533K





IMG_1363[1].JPG 3306K







IMG_1366[1].JPG 3096K




1p3




IMG_1369[1].JPG
2667K




IMG_1361[1].JPG 3417K






IMG_1364[1].JPG 3030K





IMG_1367[1].JPG 2718K





IMG_1362[1]:JPG 3720K

W2





Steven Yamasald - 5PSS3P1 <sloven.yamazald@gsa.gov:

2 of 2

1 message

David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>
To: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Mon, Nov 25, 2013 at 1:35 PM

David Kamrowski
Property Manager
GSA/PBS Michigan Property Management Operations Branch
74 N. Washington Avenue, Room 2-1-6
Battle Creek, MI 49037
269-425-3353, (b) (6) fax 269-961-7345

david.kamrowski@gsa.gov


www.gsa.gov/hdifedctr

3 attachments



IMG_1362[2].JPG 3720K

M2



IMG_1365[2].JPG 2692K



IMG_1368[1].JPG 3179K



Re: Fwd: bcph5

Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Mon, Nov 25, 2013 at 8:46 AM

To: Jerry Carter < Jerry. Carter@smithgroupjjr.com>, Steve Adams < act1001@aol.com>, Dave Kamrowski <david.kamrowski@gsa.gov>, Kathern Williams <kathern.williams@gsa.gov>

On Nov 25, 2013 8:44 AM, "Steven Yamasaki - 5PSSC1B" < steven.yamasaki@gsa.gov> wrote:

Please have your sub send in a revised shop drawing

Thank you

On Nov 25, 2013 8:32 AM, "ctaylor@caasti.com" <ctaylor@caasti.com> wrote:

5 I will have a piece made for the handrail that extends the 12" you would like. It will take at lease 3 weeks.

On November 21, 2013 at 2:51 PM Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov> wrote:

Referring to the attachment please clarify if the line pointed to is the walkway or not?

Steve

----- Forwarded message -----

From: P05R5P-CHICAG58 < P05R5P-CHICAG58@gsa.gov>

Date: Thu, Nov 21, 2013 at 1:49 PM

Subject: bcph5

To: "STEVEN.YAMASAKI@GSA.GOV" < Steven.yamasaki@gsa.gov>

Please open the attached document. This document was digitally sent to you using an HP Digital Sending device.

Steve Yamasaki Project Manager, MISC Technical team

GSA, PBS, Great Lakes Region, PMSC

230 South Dearborn Street Suite 3300

Chicago, IL 60604

(312) 353-1256 (b) (6) fax (312) 353-0240

steven.yamasaki@gsa.gov

Candice Taylor

CAASTI Contracting Services, Inc.

19115 West Eight Mile Rd

Detroit, MI 48219

313-535-9891 office / 313-535-9896

Every situation properly perceived becomes an opportunity



Steven Yamasaki - SPRSCIB serven yamasaki@gsc.gov-

Fwd: Fwd:

1 message

Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Thu, Nov 21, 2013 at 1:39 PM

To: Daniel Kammann daniel.kammann@gsa.gov

Please refer to the last page of the attachment. I nearly spit out my lunch when I read her email!

Steve

----- Forwarded message -----

From: Jerry Carter < Jerry . Carter@smithgroupjjr.com>

Date: Thu, Nov 21, 2013 at 10:29 AM

Subject: RE: Fwd:

To: Steven Yamasaki - 5PSSC1B < steven.yamasaki@gsa.gov>

Cc: "act1001@aol.com" <act1001@aol.com>, Dave Kamrowski <david.kamrowski@gsa.gov>

See attached approved shop drawings for building 1 railings.

The installation of this railing does not match the shop drawings. The shop drawings indicate the railing post in the sidewalk, which would allow the extension to be 12'' (2'' post + 10'' extension) from the last step. The installation does not meet code.

From: Steven Yamasaki - 5PSSC1B [mailto:steven.yamasaki@gsa.gov]

Sent: Thursday, November 21, 2013 10:06 AM

To: Jerry Carter

Cc: act1001@aol.com; Dave Kamrowski

Subject: Fwd:

Jerry: Can you comment and forward the approved shop drawing please.

Steve

----- Forwarded message -----

From: David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>

Date: Thu, Nov 21, 2013 at 8:48 AM

Subject: Fwd:

To: Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov>

Steve,

This is the hand rail demonstrated on A107, lower right corner.

Is this what the submittal showed?

These are new steps and the original location of the rail should not have been a contributing factor.

Two potential issues. The leading edge usually protrudes 12" beyond the end of the step and I would have expected the lower post to have been in the sidewalk not the step. I do not take issue with the post being in the step, it makes sidewalk snow removal easier for us, but the extension should be manufactured appropriately(if it isn't)

Second issue and the most important, look at the way the extension is attached to the post. Most applications the lower extension is aligned with the lower rail. The other new rails do, why doesn't this one? Please check the submittal to ensure this rail adheres to the submittal as approved.

Other than that, the hand rails at the front of Bldg 1 are installed and look like a good.

Thanks

David Kamrowski
Property Manager, Battle Creek Field Office
GSA, PBS Great Lakes Region, MISC, PMSC
Hart-Dole-Inouye Federal Center, 74 N. Washington Ave.
Battle Creek, Michigan 49037-3086
269-425-3353, (b) (6) fax 269-961-7345
david.kamrowski@gsa.gov
www.gsa.gov/hdifedctr

Steve Yamasaki

Project Manager, MISC Technical team

GSA, PBS, Great Lakes Region, PMSC

230 South Dearborn Street Suite 3300

Chicago, IL 60604

(312) 353-1256 (b) (6) fax (312) 353-0240

steven.yamasaki@gsa.gov

Steve Yamasaki Project Manager, MISC Technical team GSA, PBS, Great Lakes Region, PMSC 230 South Dearborn Street Suite 3300 Chicago, IL 60604



Sieven Yanneseki - SPSSEPT Koleven yarnaseki@gsa.gov

Re: Fwd: bcph5

Torossage

Steven Yamasaki - 5PSS3P1 <steven.yamasaki@gsa.gov>

Tue, Nov 26, 2013 at 11:26 AM

To: "ctaylor@caasti.com" <ctaylor@caasti.com>

Cc: Jerry Carter <Jerry.Carter@smithgroupjjr.com>, "act1001@aol.com" <act1001@aol.com>, Dave Kamrowski <david.kamrowski@gsa.gov>, Kathern Williams - 5P2PQBC <kathern.williams@gsa.gov>, "Mariah C. McGunigle" <mariah.mcgunigle@gsa.gov>

My comments after looking at pictures from Dave K. on the handrails:

- 1. at stairway A the lower rail does not line up with the lower end of the extension as shown on approved shop drawing 1R4,
- 2. at SW stairway the installed handrail does not match the approved shop drawing 1R2. Note that the shop drawing shows 3 not 4 risers as exists. Please redo rail or submit new shop drawing for approval,
- 3. at SE stairway the installed handrail does not match the approved shop drawing 1R1, Note that the shop drawing shows 3 not 4 risers as exists. Please redo rail or submit new shop drawing for approval.

Steve

On Mon, Nov 25, 2013 at 8:32 AM, ctaylor@caasti.com <ctaylor@caasti.com> wrote:

I will have a piece made for the handrail that extends the 12" you would like. It will take at lease 3 weeks.

On November 21, 2013 at 2:51 PM Steven Yamasaki - 5PSSC1B <steven.yamasaki@gsa.gov> wrote:

Referring to the attachment please clarify if the line pointed to is the walkway or not?

Steve

-- Forwarded message -----

From: P05R5P-CHICAG58 < P05R5P-CHICAG58@gsa.gov>

Date: Thu, Nov 21, 2013 at 1:49 PM

Subject: bcph5

To: "STEVEN.YAMASAKI@GSA.GOV" < Steven.yamasaki@gsa.gov>

Please open the attached document. This document was digitally sent to you using an HP Digital Sending device.

Steve Yamasaki Project Manager, MISC Technical team GSA, PBS, Great Lakes Region, PMSC 230 South Dearborn Street Suite 3300 Chicago, IL 60604

(312) 353-1256 (b) (6) fax (312) 353-0240

steven.yamasaki@gsa.gov

Candice Taylor

CAASTI Contracting Services, Inc.

19115 West Eight Mile Rd

Detroit, MI 48219

313-535-9891 office / 313-535-9896

Every situation properly perceived becomes an opportunity

Steve Yamasaki
Project Manager,MISC Technical team
GSA, PBS, Great Lakes Region, PMSC
230 South Dearborn Street Suite 3300
Chicago, IL 60604
(312) 353-1256 (b) (6) fax (312) 353-0240
steven.yamasaki@gsa.gov



Service Valuebille - Statistic value top to Schilling as give

Re: Stairway A

Steven Yamasaki - 5PSS3P1 <steven.yamasaki@gsa.gov>

Fri, Dec 6, 2013 at 9:10 AM

To: "ctaylor@caasti.com" <ctaylor@caasti.com>, Jerry Carter <Jerry.Carter@smithgroupjjr.com>,

"act1001@aol.com" <act1001@aol.com>, Dave Kamrowski <david.kamrowski@gsa.gov>

Cc: "Williams - 5P2PQBC, Kathern" <kathern.williams@gsa.gov>

Yes. Please either resubmit a shop drawing for approval or provide a new or revised handrail in accordance with the currently approved shop drawing.

Steve

On Wed, Dec 4, 2013 at 1:53 PM, ctaylor@caasti.com <ctaylor@caasti.com> wrote:

Steve, As I stated in our conversation today, I will have the revised drawings to you this week. As it relates to Stairway A, please see the following explanation provided from my installer:

Item #1, The cad drawing shows the lower extension lining up but in reality the bend was too tight (not enough room for bending) to make on the aluminum pipe line up with the adjacent member, we ran it straight into the post for that reason and for conformity

Please let me know how you would like me to proceed. Do you need a revision to this shop drawing as well.

Candice Taylor

CAASTI Contracting Services, Inc.

19115 West Eight Mile Rd

Detroit, MI 48219

313-535-9891 office / 313-535-9896

Every situation properly perceived becomes an opportunity

Steve Yamasaki Project Manager,MISC Technical team GSA, PBS, Great Lakes Region, PMSC 230 South Dearborn Street Suite 3300 Chicago, IL 60604





·Storen Varianski - SPSESDA I dovorajemanski Gysalyor

RE: 7E -1R4 Railing Revised Submittal

T messags.

Jerry Carter < Jerry.Carter@smithgroupjjr.com>
To: Steven Yamasaki - 5PSS3P1 < steven.yamasaki@gsa.gov>

Tue, Dec 17, 2013 at 11:42 AM

Thanks Steve, but I'm waiting on a hard copy from Caasti.

From: Steven Yamasaki - 5PSS3P1 [mailto:steven.yamasaki@gsa.gov]

Sent: Tuesday, December 17, 2013 11:25 AM

To: Jerry Carter

Subject: Fwd: 7E -1R4 Railing Revised Submittal

------ Forwarded message -----

From: ctaylor@caasti.com <ctaylor@caasti.com>

Date: Tue, Dec 10, 2013 at 9:45 AM

Subject: 7E -1R4 Railing Revised Submittal

To: "Yamasaki - 5PSSC1B, Steven" <steven.yamasaki@gsa.gov>

Cc: "Carter, Jerry" < Jerry. Carter@smithgroupjjr.com>

Please see attached.

Candice Taylor

CAASTI Contracting Services, Inc.

19115 West Eight Mile Rd

Detroit, MI 48219

313-535-9891 office / 313-535-9896

Every situation properly perceived becomes an opportunity

Steve Yamasaki

Project Manager, MISC Technical team

GSA, PBS, Great Lakes Region, PMSC

230 South Dearborn Street Suite 3300

Chicago, IL 60604

(312) 353-1256 (b) (6) fax (312) 353-0240

steven.yamasaki@gsa.gov



BC phase 5 building 1 handrail Created by: Steven Yamasaki - 5PSS3P1 · Your response: Yes, I'm going

11am - 12pm (Central Time)

Rooms, etc.

✓ R05-PBS-Dearborn-Bridge Line 3 -877-923-9144 - (Leader Passcode 7390465) Passcode 8181244

Date

Wed Apr 2, 2014

Guests

✓ Steven Yamasaki - 5PSS3P1

✓ David Kamrowski - 5PSSCB

Kathern Williams - 5P2PQBC

Where

R05-PBS-Dearborn-Bridge Line 3 - 877-923-9144 - (Leader Passcode 7390465) Passcode 8181244

Description

BC phase 5 building 1 handrail

My Notes

•



Steven Yamasaki - 5PSS3P1 <steven.yamasaki@gsa.gov>

Re: Mock Schedule

1 message

David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>

Wed, Apr 9, 2014 at 10:41 AM

To: Steven Yamasaki - 5PSS3P1 <steven.yamasaki@gsa.gov>

Cc: Kathern Williams - 5P2PQBC <kathern.williams@gsa.gov>, Jerry Carter <Jerry.Carter@smithgroupjjr.com>

My comments on handrail "A" are as follows:

The constructed hand rail differs from the submital in the following way. The lower rails do not align at the point where the lower rail descends to the lower post and the lower point the extension meets the lower post. The submital shows a slight radius on the extension as it connects to the post to soften the change in slope angles. The extension butts at a 90 degree angle where the lower rail hits the post at an assumed 24.8 degree angle (based on the bevel shown on the submital). This gives the appearance that the lower rail aligns mid way through the extension rail and is mis aligned by half the diameter of the extension, making the rail un-acceptable.

On Tue, Apr 8, 2014 at 4:38 PM, Steven Yamasaki - 5PSS3P1 <steven.yamasaki@gsa.gov> wrote:

my comments below in CAPS

- 1. There is only one rail in question. First we have to come to the conclusion that there is a problem with the rail. If we come to that conclusion, then a method of resolution will be addressed. Once we have come to a method of resolution, then a time table to execute said resolution will be presented to you. DAVE TO REVIEW RAIL A, TONY TO REVIEW 2 SIDE RAILS.
- 2. Yes. EXIT TO BE OUT 6 WEEKS IS UNACCEPTABLE.
- 3. Yes. EXIT TO BE OUT 9+ WEEKS IS UNACCEPTABLE
- 4. No, exit #8 railing will remain in place until fabrication of new railing is close to completion.
- 5. No, railing that is currently protecting courtyard will stay in place until new railing is installed.
- 6. Yes. CONTRACT TIME ENDS 31JULY2014.
- 7. The responses will be forwarded to The Smith Group. PLEASE CC ME ON SUBMITTAL TO S-G.
- 8. We are schedule to discuss this topic with Mariah during today's conference call. PLEASE CC ME ON SUBMITTAL TO S-G AS AGREED.

On Wed, Apr 2, 2014 at 9:12 AM, Kathern Williams - 5P2PQBC <kathern.williams@gsa.gov> wrote: response to mock schedule

Kathern M. Williams
Contracting Officer
Chicagoland & Customer Projects Contracting Branch
GSA, PBS, Great Lakes Region, Acquisition Management Division

230 S. Dearborn Street, Ste. 3300 Chicago, IL 60604 (312) 886-1060

(b)(f)(012) 000 000 1

Fax (312) 353-9628 kathern.williams@gsa.gov

----- Forwarded message -----

From: Tony Taylor < TTaylor@caasti.com>

Date: Wed, Apr 2, 2014 at 9:11 AM Subject: RE: Mock Schedule

To: Kathern Williams - 5P2PQBC <kathern.williams@gsa.gov>

Cc: ctaylor@caasti.com

Good Morning Kathern,

Below are responses to Steve Y's comments.

- 1. There is only one rail in question. First we have to come to the conclusion that there is a problem with the rail. If we come to that conclusion, then a method of resolution will be addressed. Once we have come to a method of resolution, then a time table to execute said resolution will be presented to you.
- Yes.
- 3. Yes.
- 4. No, exit #8 railing will remain in place until fabrication of new railing is close to completion.
- 5. No, railing that is currently protecting courtyard will stay in place until new railing is installed.
- 6. Yes.
- 7. The responses will be forwarded to The Smith Group.
- 8. We are schedule to discuss this topic with Mariah during today's conference call.

If you have any questions please don't hesitate to contact me.

Thanks.

Tony A. Taylor

Sr. Estimator / Project Manager

Caasti Contracting Services

19115 W	est Eight Mile Road						
Detroit,	MI 48219		:1, , · · ·		*.*	•	
(313) 53	5-9891 Office		·				
(313) 53	5-9896 Fax					7	
ttaylor@	@caasti.com		÷				
		The state of the					
Sent: Tu To: Tony	athern Williams - 5P2P Jesday, April 01, 2014 5 y Taylor; ctaylor : Mock Schedule	_	n.williams@g	sa.gov]			·
Tony,					A A		
Below a to my at	re Steve Y's comments tention.	regarding your mock	schedule. Ple	ase addre	ss and retu	ırn revised	schedule
1. Wha	t about the replacement	rails at the building 1	areas?,		e e		
2. Bldg rails?,	#2a exit-still rebuilding	then measuring for ha	indrails so 30 d	days (6 we	eeks) open	with temp	orary
	#7-being repaired not re ry rails for 46 days (9+w	` —	AASTI'S option	to rebuild), but open	with appro	oved
4. Exit	#8-open with approved t	emporary rails for 41 o	days (8+weeks	s)?,			Ç [‡]
5. Cour	tyard-open with approve	d temporary rails for 8	34 days (16+ w	/eeks)?	at 1		d .
6. Does	s the *** mean that the r range,	nentioned work will be	e performed be	tween Ma	y 5 and Se	ptember 1	7? That's

7. where are we on the metal arch detail for the arches submittal and,

8. where are we on the counter flashing detail at buildings 31 and building 1a corridor?

Kathern M. Williams

Contracting Officer

Chicagoland & Customer Projects Contracting Branch

GSA, PBS, Great Lakes Region, Acquisition Management Division

230 S. Dearborn Street, Ste. 3300

Chicago, IL 60604

(312) 886-1060



Fax (312) 353-9628

kathern.williams@gsa.gov

Steve Yamasaki
Project Manager,MISC Technical team
GSA, PBS, Great Lakes Region, PMSC
230 South Dearborn Street Suite 3300
Chicago, IL 60604
(312) 353-1256 (b) (6) fax (312) 353-0240
steven.yamasaki@gsa.gov

David Kamrowski
Property Manager
Grand Rapids/Battle Creek Field Office
Michigan Property Management Operations Branch
GSA/PBS Northern Service Center Operations Division
74 N. Washington Avenue, Room 2-1-6, Battle Creek, MI 49037
269-425-3353, (b) (6) fax 269-961-7345
david.kamrowski@gsa.gov
www.gsa.gov/hdifedctr



Steven Yamasaki - 5PSS3P1 <steven.yamasaki@gsa.gov>

Re: Mock Schedule

1 message

David Kamrowski - 5PSSCB <david.kamrowski@gsa.gov>

Wed, Apr 9, 2014 at 10:50 AM

To: Steven Yamasaki - 5PSS3P1 < steven.yamasaki@gsa.gov>

Cc: Kathern Williams - 5P2PQBC <kathern.williams@gsa.gov>, Jerry Carter <Jerry.Carter@smithgroupjjr.com>

See photo of actual hand rail "A" in Steve Adams report of 12/30/13 sent on 1/2/14. Picture is on page 7. It looks worse in person.

On Tue, Apr 8, 2014 at 4:38 PM, Steven Yamasaki - 5PSS3P1 <steven.yamasaki@gsa.gov> wrote:

my comments below in CAPS

- 1. There is only one rail in question. First we have to come to the conclusion that there is a problem with the rail. If we come to that conclusion, then a method of resolution will be addressed. Once we have come to a method of resolution, then a time table to execute said resolution will be presented to you. DAVE TO REVIEW RAIL A, TONY TO REVIEW 2 SIDE RAILS.
- 2. Yes. EXIT TO BE OUT 6 WEEKS IS UNACCEPTABLE.
- Yes. EXIT TO BE OUT 9+ WEEKS IS UNACCEPTABLE
- 4. No, exit #8 railing will remain in place until fabrication of new railing is close to completion.
- 5. No, railing that is currently protecting courtyard will stay in place until new railing is installed.
- Yes. CONTRACT TIME ENDS 31JULY2014.
- 7. The responses will be forwarded to The Smith Group. PLEASE CC ME ON SUBMITTAL TO S-G.
- 8. We are schedule to discuss this topic with Mariah during today's conference call. PLEASE CC ME ON SUBMITTAL TO S-G AS AGREED.

On Wed, Apr 2, 2014 at 9:12 AM, Kathern Williams - 5P2PQBC <kathern.williams@gsa.gov> wrote: response to mock schedule

Kathern M. Williams
Contracting Officer
Chicagoland & Customer Projects Contracting Branch
GSA, PBS, Great Lakes Region, Acquisition Management Division
230 S. Dearborn Street, Ste. 3300
Chicago, IL 60604
(312) 886-1060

Fax (312) 353-9628 kathern.williams@gsa.gov

-- Forwarded message -----

From: Tony Taylor <TTaylor@caasti.com>

Date: Wed, Apr 2, 2014 at 9:11 AM Subject: RE: Mock Schedule

To: Kathern Williams - 5P2PQBC <kathern.williams@gsa.gov>

Cc: ctaylor@caasti.com

Good Morning Kathern,

Below are responses to Steve Y's comments.

- 1. There is only one rail in question. First we have to come to the conclusion that there is a problem with the rail. If we come to that conclusion, then a method of resolution will be addressed. Once we have come to a method of resolution, then a time table to execute said resolution will be presented to you.
- 2. Yes.
- Yes.
- 4. No, exit #8 railing will remain in place until fabrication of new railing is close to completion.
- 5. No, railing that is currently protecting courtyard will stay in place until new railing is installed.
- 6. Yes.
- 7. The responses will be forwarded to The Smith Group.
- 8. We are schedule to discuss this topic with Mariah during today's conference call.

If you have any questions please don't hesitate to contact me.

Thanks.

Tony A. Taylor

Sr. Estimator / Project Manager

Caasti Contracting Services

19115 West Eight Mile Road

Detroit, MI 48219

(313) 535-9891 Office

(313) 535-9896 Fax

ttaylor@caasti.com

From: Kathern Williams - 5P2PQBC [mailto:kathern.williams@gsa.gov]

Sent: Tuesday, April 01, 2014 5:00 PM

To: Tony Taylor; ctaylor **Subject:** Mock Schedule

Tony,

Below are Steve Y's comments regarding your mock schedule. Please address and return revised schedule to my attention.

- 1. What about the replacement rails at the building 1 areas?,
- 2. Bldg #2a exit-still rebuilding then measuring for handrails so 30 days (6 weeks) open with temporary rails?,
- 3. Exit #7-being repaired not rebuilt (although it is CAASTI'S option to rebuild), but open with approved temporary rails for 46 days (9+weeks)?,
- 4. Exit #8-open with approved temporary rails for 41 days (8+weeks)?,
- 5. Courtyard-open with approved temporary rails for 84 days (16+ weeks)?
- 6. Does the *** mean that the mentioned work will be performed between May 5 and September 17? That's quite a range,
- 7. where are we on the metal arch detail for the arches submittal and,
- 8. where are we on the counter flashing detail at buildings 31 and building 1a corridor?

Kathern M. Williams

Contracting Officer

Chicagoland & Customer Projects Contracting Branch

GSA, PBS, Great Lakes Region, Acquisition Management Division

230 S. Dearborn Street, Ste. 3300

Chicago, IL 60604

(312) 886-1060

(b) (6)

Fax (312) 353-9628

kathern, williams@gsa.gov

Steve Yamasaki
Project Manager,MISC Technical team
GSA, PBS, Great Lakes Region, PMSC
230 South Dearborn Street Suite 3300
Chicago, IL 60604
(312) 353-1256 (b) (6) fax (312) 353-0240
steven.yamasaki@gsa.gov

David Kamrowski
Property Manager
Grand Rapids/Battle Creek Field Office
Michigan Property Management Operations Branch
GSA/PBS Northern Service Center Operations Division
74 N. Washington Avenue, Room 2-1-6, Battle Creek, MI 49037
269-425-3353, (b) (6) fax 269-961-7345
david.kamrowski@gsa.gov
www.gsa.gov/hdifedctr